

**PROJECT PHOTOS**



**Construction of exterior wood framing (01/06/2021)**



**Installation of LVL joists (01/08/2021)**



**Interior and exterior wood framing installation  
(01/14/2021)**



**Interior and exterior wood framing installation  
(01/14/2021)**



**Interior and exterior wood framing installation  
(01/15/2021)**



**Interior wood construction (01/20/2021)**

**Town of Acton, MA**  
North Acton Fire Station



**Interior and exterior wood framing installation (01/20/2021)**



**Exterior wood construction (01/22/2021)**



**Interior wood framing installation (01/22/2021)**



**Start of geothermal well drilling (01/22/2021)**



**Interior wood framing installation (01/27/2021)**



**Saw cutting for insulation installation (01/27/2021)**



**Overview of exterior wood framing (01/27/2021)**



**Geothermal well drilling (01/29/2021)**



**Picking for roof supplies (01/29/2021)**



**North side of wood construction (01/29/2021)**



**Interior LVL framing (02/03/2021)**



**Interior column box slab poured (02/03/2021)**

**Town of Acton, MA**  
North Acton Fire Station



**Interior LVL framing (02/03/2021)**



**Overview of exterior wood framing (02/05/2021)**



**Overview of wood construction from west side of apparatus bay (02/05/2021)**



**Interior wood framing (02/05/2021)**



**Waterproofing installed on LVL roof area (02/05/2021)**



**Installation of waterproofing over insulation on low roof area (02/05/2021)**