



Overview of wood construction from southeast



Snow removed from apparatus bay



Overview of building from west side



Interior wood framing and LVL corrective action



Installation of waterproofing in low roof area



Waterproofing and mechanical curb installed on living area



Electrical rough work on east side of building



Concrete placed in column box