




Overview of east side



Overview of apparatus bay area



Northern exterior wall of electrical sub room between Line 6.5 and 5.



Steel beam header at gear room looking west to Line 5. Holes drilled in beam for ledger installation per structural engineer direction



Masonry apparatus bay door frame



Typical construction of interior masonry wall



HVAC hanger installed in low roof area



Line 5 masonry installation