



PMA Consultants


NAFS Photo Log 04.01.2021



Overview of east side



Overview of building from southwest side of site



Corrected rip rap at southwest construction entrance



Corrected erosion and sediment control near north side of building



PMA Consultants


NAFS Photo Log 04.01.2021



North side of apparatus bay



Steel roof joists in apparatus bay looking south from north side




Northwest side of western mezzanine



Steel roof joists in apparatus bay looking north from south side




Western mezzanine



West side of building



Metal roof decking on western mezzanine



MEP in fitness room




PMA Consultants

NAFS Photo Log 04.01.2021



HVAC and electrical in bunk areas



Geothermal mechanical in mechanical room



Mock up at job site trailer



Mock up at job site trailer