



Overview of east side



Overview of building from southwest side of site



Fencing and crushed stone at southeast construction entrance



AVB and masonry facade installation at mock-up



North side of apparatus bay with installed AVB



Steel roof joists in apparatus bay looking southwest



Masonry construction in dirty laundry room



Sheet metal installed at steel columns on south face of apparatus bay for AVB preparation.



MEP rough-ins



Mechanical pads installed in mechanical room



MEP rough-ins in gear room



Shower installation