



Overview of site from southwest



Overview of east side of building




MEP rough-ins on east side



Mechanical room



MEP rough-ins at gear room



MEP rough-ins on east side



Façade installation on north side



Façade installation at transitional low roof



Façade installation on south side



Flashing installed on north side



Interior wall in dirty laundry room




Metal deck roof installed at dirty laundry room




Reinforcing installation for mezzanine slab



Reinforcing installation for mezzanine slab looking towards south stairs



Reinforcing installation for dirty laundry roof



Typical shoring underside for mezzanine slab