



Overview of building from southeast



Overview of building from north




Overview of building from southwest



Installation of exterior electrical cabinets



Drywall and frames installed at vestibule



Overview of apparatus bay from mezzanine




Typical interior sealant installed




Typical exterior sealant installed




Mechanical room



Mechanical room



Soffit at eastern roof access ladder



Vehicle exhaust system installation



Officer's bunk room



Vestibule



Trench excavation for fire alarm/telecom/IT conduits on south side (Part of PR#009)



Excavation for north parking lot site lighting and conduits