



Overview of building from southeast



Overview of main entrance



Overview of west side of building



Overview of apparatus bay south side



PVC siding on southeast side of building



Typical PVC to cast stone interface




Overview of apparatus bay



Exterior electrical cabinets and meter



Typical vapor retarder installed at exterior soffits




Hole cored through CMU wall for dirty laundry room HVAC condensate line



Fire alarm equipment installation in emergency electrical room



BDA equipment installation in emergency electrical room



Backflow preventer in mechanical room relocated per Water District



Interior joint sealant installed at bunk room windows



Fire alarm master box at main entrance



Backflow preventer at mechanical mezzanine to be relocated and bypass removed