



Overview of building from southeast



Overview of building from northwest



Overview of building from northeast



Overview of building from southwest



Septic tank excavation



Septic tank installation



Well drilling



More well drilling



Garage being painted



Tile grouting in bathroom



Roof flashing installation



Lighting installation